

5/019/07 2



AI. Gypsum dust in a small drainage adjacent to the north side of the pit, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23.




AJ. North side of the gypsum stockpile, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 6-13-96.

5/05/072




A. First measurement of Western Clay Company's access road, .3 mile east of the county road in T.24S., R.7E., Section 15, notice UTU-73779. 6-13-96.




B. Closeup of first measurement at 13.5 feet in width, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 15. 6-13-96.

5/015/072



C. Second measurement of Western Clay Company's access road, .6 mile east of the county road in T.24S., R.7E., Section 15, notice UTU-73779. 6-13-96.



D. Closeup of second measurement at 14.0 feet in width, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 15. 6-13-96.

5/015/072



E. Third measurement of Western Clay Company's access road, .9 mile east of the county road in T.24S., R.7E., Section 15, notice UTU-73779. 6-13-96.



F. Closeup of the third measurement at 14.25 feed wide, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 15, 6-13-96.

5/015/072




G. Fourth measurement of Western Clay Company's access road, 1.2 miles east of the county road in T.24S., R.7E., Section 14. notice UTU-73779. 6-13-96.




H. Closeup of fourth measurement, 14.25 feet wide, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 14. 6-13-96.

5/05/072




I. Fifth measurement of Western Clay Company's access road, 1.5 miles east of the county road in T.24S., R.7E., Section 14, notice UTU-73779. 6-13-96.



J. Closeup of fifth measurement, 13.25 feet in width, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 6-13-96.

5/019/072



K. Sixth measurement of Western Clay Company's access road, 1.8 miles east of the county road, 15.0 feet in width, notice UTU-73779 in T.24S., R.7E., Section 23. 6-13-96.



L. Access road just east of the sixth measurement, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 6-13-96.

S/015/072



M. Entrance to Western Clay Company's Lone Tree Wedge gypsum mine, notice UTU-73779 in T.24S., R.7E., Section 23. 6-13-96.



N. Fuel tank at the western end of the mine, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 6-19-96.

S/015/072




O. Bulldozer parked at the west end of the pit, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 6-13-96.



P. Small gypsum stockpile adjacent and southwest of the bulldozer, Western Clay Company, notice UTU-73779 in T.23S., R.7E., Section 23. 6-13-96.

5/019/072



Q. Gypsum stockpile in the center of the pit at the west end, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 6-13-96.



R. North side of the pit, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 6-13-96.

5/015/072



S. North side of the pit, just north of the stockpile, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 6-13-96.



T. South end of the pit, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23, 6-13-96.

5/015/072



U. Gypsum stockpile, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 6-13-96.



V. Loader parked at the east end of the stockpile, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 6-13-96.

5/015/072



W. East end of the gypsum stockpile, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 6-13-96.



X. East end of the pit, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 6-13-96.

5/015/072



Y. North side of the pit on the east end, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 6-13-96.



Z. ^K Looking north along the east end of the pit, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 6-13-96.

5/015/072



AA. Southeast corner of the pit, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 6-13-96.



AB. Gypsum dust in the wash just east of the pit, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 6-13-96.

5/015/072



AC. Looking west along the south side of the pit, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 6-13-96.



AD. Southeast corner of the pit looking east, Western Clay Company, notice UTU-73779 in T.23S., R.7E., Section 23. 6-19-96.

5/019/072



AE. Gypsum dust spilling into the wash on the east end of the pit, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 6-13-96



AF. Gypsum dust in the cryptogamic soil on the north side of the pit at the east end, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 6-13-96.